شرکت گام الکتریک

(سهامی خاص – تأسیس ۱۳۷۳)

تحت لىسانس MERKLE آلمان



THREE PHASE SYNERGIC MIG / MAG WELDING UNITS

TYPE: Easy MIG

Models: Easy MIG 501T, Easy MIG 601T

- Easy Arc energy adjustment by a single potentiometer with no requirement to adjust multiple welding parameters like voltage, wire speed ,... (intelligent control parameters)
- Synergic wire feed speed control adapts automatically wire feed speed by selecting the appropriate welding voltage
- Welding programs for steel, stainless steel, Aluminium, brazing, Flux cored
- Digital display for indicating voltage and welding current and wire speed
- Soft arc by means of creep start system
- High Duty Cycle for heavy industries
- Service & warranty



دستگاه های جوشکاری سه فاز میگ سینرجیک

تىپ Easy MIG

مدل های:Easy MIG 601T,Easy MIG 501T

- 🕹 تنظیم آسان انرژی فقط بوسیله یک پتانسپومتر بدون نیاز به تنظیم جزء به جزء یار امترهای جوشکاری مانند ولتاژ، سرعت سیم و ... (تنظیم اتوماتیک و هوشمند یار امترها)
 - 💠 تنظیم سرعت سیم که به صورت اتوماتیک که با تنظیم ولتاژ جوشکاری هم زمان تنظیم می گردد.
 - 🛶 برنامه های از پیش تنظیم شده برای جوشکاری فولاد ،استینلس استیل و آلومینیوم، Brazing و Flux Cored 🔸
 - 💠 مجهز به نمایشگر دیجیتال جهت نمایش ولتاژ و جریان 🛮 قوس ، سرعت سیم
 - 💠 شروع قوس نرم توسط سیستم Creep Strat
 - 🔸 Duty Čycle بسیار بالا جهت کارهای سنگین صنعتی
 - 🔸 دوره ضمانت با پشتیبانی و خدمات





MMA





MIG/MAG







PLASMA









SAW









شرکت گام الکتریک

(سهامی خاص – تأسیس ۱۳۷۳)

تعت لىسانس MERKLE آلمان



دستگاه های جوشکاری سه فاز MIG/MAG SYNERGICMIG/MAGWELDING MACHINESسینرجیک THREE PHASE SYNERGICMIG/MAGWELDING MACHINES

Easy MIG 501T, Easy MIG 601T

Easy MIG synergic MIG/MAG machine has been designed under the

licence of MERKLE, Germany. By selecting the type and diameter of wire and adjusting a single potentiometer, all welding parameters like voltage, current and wire feed speed will be adjusted automatically.

EXCELLENT FEATURES OF MACHINES:

- Suitable for Aluminium, iron, stainless steel welding and thin or thick sheets and pipes

Models:

- 2 stroke /4 stroke
 Gas test and wire insertion button
- Ability to control of wire feed speed (in manual mode) and arc trim (in synergic mode) on machine/wire feeder
 Spot welding & Stitch welding are available
 Burn Back adjustment to avoid wire stick to contacttipor work piece

- Burn Back adjustment to avoid wire stick to contactipor work piece Digital display for arc voltage and wire feed speed Hold function ability to display last welding parameters Capability of welding in Synergic and Manual mode Overheating protection Including water cooling system for torch cooling Energy saving ability each unit (fan and cooling unit) work when is needed.

ACCESSORIES

- Wire feeder
- Earth clamp with cable
- Water cooled or air cooled MIG torch Water cooled or air cooled interconnection cable

CHNICAL DATA

Water coolant system

OPTIONAL

- Gas regulator Gas heater
- Four-wheel for wire feeder
- Automatic welding mask
- TEDAC torch

Wire Burn Back

Gas Test

Material Selection

دستگاه پارس میگ سینرجیک تیپMIG Easy با بهره گیری از فن آوری پیشرفته صنایع جوش MERKLE آلمان و تحت لیسانس آن طراحی و ساخته شده است.در این دستگاه ابتدا نوع سیم جوش و قطر آن مشخص می گردد سپس با تنظیم تنها یک پتانسیومتر، متغیرهای ولتاثر، شدت جریان و سرعت خروج سیم به صورت اتوماتیک تنظیم خواهند شد.

ویژگیهای برجسته دستگاه ها :

- مناسب برای جوشکاری آلومینیوم،آهن، استینلس استیل روی ورقهای نازک یا ضخیم و
 - انجام شروع و پایان جوِشکاری با حق انتخاب یک یا دو بار فشردن شستی تورچ
- - قابلیت جوشکاری Stitch Welding & Spot Welding
- قابلیت تنظّیم Burn Backجهت جلو گیری از چسبیدن سیم به نازل تورچ یا به قطعه کار

 - نمایشگر دیجیتال ولتاژ قوس و سرعت سیم مجهز به LED : Hold Function جهت نمایش آخرین پارامترهای جوشکاری
 - قابلیت کار در دو حالت سینرجیک (Synergic) و تَنظیمْ دُستَی (Manual) حفاظت در مقابل اضافه بار
 - دارای سیستم آب خنک جبت خنک سازی تورچ
- دارای قابلیت صرفه جویی در انرژی (کنترل فن دستگاه و یونیت آب خنک), عملکرد هریک تنها در زمان مورد نیاز صورت خواهد گرفت

ضمائم

وايرفيدر

مدل های:

- کابل و انبر اتصال
- تورچ میگ آب خنک یا هوا خنک
 - ليفه آب خنک يا هواخنک
- یونیت آب خنک(ضمیمه دستگاه های آب خنک)

در صورت سفارش

- رگولاتور گاز
- گرم کن گاز
- وايرفيدر چرخدار
- ماسک اتومات جوشکاری تورچ TEDAC

Welding Control Step		Continuous	Continuous
Welding Range	Α	25-450	25-600
Welding Current at 60% Duty Cycle (Other duty cycle on request)		450	550
Welding Current at 100% Duty Cycle	Α	400	490
No. Load Voltage	V	10-53	10-60
Installed Power	KVA	27	40
Setting Energy		unit/on the TEDAC to	tton adjusting on the rch/4 programs on the C torch
Arc Length		Automatio	Adjusting
Arc Trim		Variable Re	sistor ±30%
Operation Mode			ke / Interval / Spot

Easy MIG 501T

Easy MIG 601T

Adjustable Inside Steel /Stainless Steel /Aluminium/Special

Button With HOLD - Function & Time

Switching

Torch Cooling		Gas /	Water
MAINS CONNECTION (Three Phase, 50Hz,	400V. Of	ther Voltage / frequenc	ies on request)
Fuse (Fast Action)	Α	D 40	D 63
Mains Cable Cross Section (Cu, Nyy) mm ²		4 x 4	4 x 6
MISCELLANEOUS			

cooling		Fan	Fan
Protection Class (Acc. to IEC529)		IP21S	IP21S
Insulation Class		Н	Н
Dimension(LxWxH)	mm	1025x 490 x 920	1025x 490 x 920
Weight	ka	170	196.5

F: Fasted action fuse D: Delayed action fuse Gaam Electric reserves the rights to change the specifications without notice. 1. First digit number of the name of machine (for ex. 1 in Easy MIG 501T) is the version of machine.

	PARS FEED		G4420E
	Operating Voltage	V	42
-	No. of Rolls		4
	Wire feed speed	m/min	0-20
]	Wire Reel		
-	Capacity	Kg	15
+	Outer Diameter	cm	30
	Wire Diameter	mm	
+	Steel		0.8-1.6
1	Aluminium		1-1.6
	Stainless Steel		0.8-1.2
+	Flux cored		1-1.6
1	Weight	Kg	13.370
1	Dimension(LxWxH)	cm	42 x 24 x 29
-	Cooling system		Air/Water

نوجه: حق تغییر کلیه مشخصات بدون اطلاع قبلی برای شرکت گام الکتریک محفوظ خواهد بود



شرکت گام الکتریک

(سهامی خاص – تأسیس ۱۳۷۳)

تعت لىسانس MERKLE آلمان



دستگاه های جوشکاری سه فاز MIG/MAG SYNERGICMIG/MAGWELDING MACHINESسینرجیک THREE PHASE SYNERGICMIG/MAGWELDING MACHINES

Easy MIG 501T, Easy MIG 601T

Easy MIG synergic MIG/MAG machine has been designed under the

licence of MERKLE, Germany. By selecting the type and diameter of wire and adjusting a single potentiometer, all welding parameters like voltage, current and wire feed speed will be adjusted automatically.

EXCELLENT FEATURES OF MACHINES:

- Suitable for Aluminium, iron, stainless steel welding and thin or thick sheets and pipes

Models:

- 2 stroke /4 stroke
 Gas test and wire insertion button
- Ability to control of wire feed speed (in manual mode) and arc trim (in synergic mode) on machine/wire feeder
 Spot welding & Stitch welding are available
 Burn Back adjustment to avoid wire stick to contacttipor work piece

- Burn Back adjustment to avoid wire stick to contactipor work piece Digital display for arc voltage and wire feed speed Hold function ability to display last welding parameters Capability of welding in Synergic and Manual mode Overheating protection Including water cooling system for torch cooling Energy saving ability each unit (fan and cooling unit) work when is needed.

ACCESSORIES

- Wire feeder
- Earth clamp with cable
- Water cooled or air cooled MIG torch Water cooled or air cooled interconnection cable

CHNICAL DATA

Water coolant system

OPTIONAL

- Gas regulator Gas heater
- Four-wheel for wire feeder
- Automatic welding mask
- TEDAC torch

Wire Burn Back

Gas Test

Material Selection

دستگاه پارس میگ سینرجیک تیپMIG Easy با بهره گیری از فن آوری پیشرفته صنایع جوش MERKLE آلمان و تحت لیسانس آن طراحی و ساخته شده است.در این دستگاه ابتدا نوع سیم جوش و قطر آن مشخص می گردد سپس با تنظیم تنها یک پتانسیومتر، متغیرهای ولتاثر، شدت جریان و سرعت خروج سیم به صورت اتوماتیک تنظیم خواهند شد.

ویژگیهای برجسته دستگاه ها :

- مناسب برای جوشکاری آلومینیوم،آهن، استینلس استیل روی ورقهای نازک یا ضخیم و
 - انجام شروع و پایان جوِشکاری با حق انتخاب یک یا دو بار فشردن شستی تورچ
- - قابلیت جوشکاری Stitch Welding & Spot Welding
- قابلیت تنظّیم Burn Backجهت جلو گیری از چسبیدن سیم به نازل تورچ یا به قطعه کار

 - نمایشگر دیجیتال ولتاژ قوس و سرعت سیم مجهز به LED : Hold Function جهت نمایش آخرین پارامترهای جوشکاری
 - قابلیت کار در دو حالت سینرجیک (Synergic) و تَنظیمْ دُستَی (Manual) حفاظت در مقابل اضافه بار
 - دارای سیستم آب خنک جبت خنک سازی تورچ
- دارای قابلیت صرفه جویی در انرژی (کنترل فن دستگاه و یونیت آب خنک), عملکرد هریک تنها در زمان مورد نیاز صورت خواهد گرفت

ضمائم

وايرفيدر

مدل های:

- کابل و انبر اتصال
- تورچ میگ آب خنک یا هوا خنک
 - ليفه آب خنک يا هواخنک
- یونیت آب خنک(ضمیمه دستگاه های آب خنک)

در صورت سفارش

- رگولاتور گاز
- گرم کن گاز
- وايرفيدر چرخدار
- ماسک اتومات جوشکاری تورچ TEDAC

Welding Control Step		Continuous	Continuous
Welding Range	Α	25-450	25-600
Welding Current at 60% Duty Cycle (Other duty cycle on request)		450	550
Welding Current at 100% Duty Cycle	Α	400	490
No. Load Voltage	V	10-53	10-60
Installed Power	KVA	27	40
Setting Energy		unit/on the TEDAC to	tton adjusting on the rch/4 programs on the C torch
Arc Length		Automatio	Adjusting
Arc Trim		Variable Re	sistor ±30%
Operation Mode			ke / Interval / Spot

Easy MIG 501T

Easy MIG 601T

Adjustable Inside Steel /Stainless Steel /Aluminium/Special

Button With HOLD - Function & Time

Switching

Torch Cooling		Gas /	Water
MAINS CONNECTION (Three Phase, 50Hz,	400V. Of	ther Voltage / frequenc	ies on request)
Fuse (Fast Action)	Α	D 40	D 63
Mains Cable Cross Section (Cu, Nyy) mm ²		4 x 4	4 x 6
MISCELLANEOUS			

cooling		Fan	Fan
Protection Class (Acc. to IEC529)		IP21S	IP21S
Insulation Class		Н	Н
Dimension(LxWxH)	mm	1025x 490 x 920	1025x 490 x 920
Weight	ka	170	196.5

F: Fasted action fuse D: Delayed action fuse Gaam Electric reserves the rights to change the specifications without notice. 1. First digit number of the name of machine (for ex. 1 in Easy MIG 501T) is the version of machine.

	PARS FEED		G4420E
	Operating Voltage	V	42
-	No. of Rolls		4
	Wire feed speed	m/min	0-20
]	Wire Reel		
-	Capacity	Kg	15
+	Outer Diameter	cm	30
	Wire Diameter	mm	
+	Steel		0.8-1.6
1	Aluminium		1-1.6
	Stainless Steel		0.8-1.2
+	Flux cored		1-1.6
1	Weight	Kg	13.370
1	Dimension(LxWxH)	cm	42 x 24 x 29
-	Cooling system		Air/Water

نوجه: حق تغییر کلیه مشخصات بدون اطلاع قبلی برای شرکت گام الکتریک محفوظ خواهد بود

